



CADILLAC CUE SCREEN REPAIR

\$129 MSRP*

THE ISSUE

ALL CUE SYSTEMS HAVE A TOUCH SCREEN WITH A GEL CENTER THAT DRIES OUT OVER TIME.

CRACKING AND LOST/ ERRATIC TOUCH RESPONSE IS VERY COMMON.

THE GM TECHNICAL BULLETIN WILL ONLY ALLOW CUE MODULE REPLACEMENT FOR \$1,500.

HOWEVER, ONLY THE TOUCH SCREEN NEEDS REPLACEMENT.

SYMPTOMS

SIGNS THAT ONLY THE TOUCH SCREEN NEEDS TO BE REPLACED:

- CRACKS, SPIDER WEB APPEARANCE
- PEELING, BUBBLING, DELAMINATION
- LOST OR ERRATIC TOUCH RESPONSE
- SCRATCHES OR COSMETIC DAMAGE

CUESCREENS OFFERS TOP QUALITY, GEL-FREE REPLACEMENT TOUCH SCREENS- AT A GREAT PRICE

FITMENT

2013-2017 ATS ATS-V
2015-2017 ESCALADE
2013-2016 SRX
2013-2017 XTS
2014-2017 CTS CTS-V
2014-2016 ELR



**IMPROVED
DESIGN**



**OVER 5,000
INSTALLED**



**5 STAR
RATED**



**USA BASED
SUPPORT**



**OEM GRADE
AND FEATURES**



**FAST
SHIPPING**



**2 YEAR
WARRANTY**



★ Shop now ★

CUESCREENS.COM



CUESCREENS@GMAIL



563.289.7276



@CUESCREENS

*MSRP is list price of the screen only. Installation labor is additional